AS9D

# **Technical specifications**


Intended use	Endodontics						
Indications for use	Endodontic apical surgery						
Description	Diamond-coated apical surgery tip, complementing the AS3D and AS6D tips, for complex cases and for the preparation of the root canal to the crown third of anterior teeth						
Tip type	Diamond-coated						
	Tip made of surgical stainless steel as per ASTM F899 - 12b						
	Surgical stainless steel contains:						
Allergenic factor	<ul><li>nickel</li><li>chromiu</li></ul>						
	Diamond polishing crimping binder alloy contains:					N.	
	• nickel					14	
Commercial reference	AS9D: F00067						
Medical class	Class of medical device: IIa according to 93/42/EEC directive					NH	
	Newtron range	P5 Range	Suprasson P5 Booster		ny Max - P-Max - nter 2 - Piezotome 2	Irrigation	
Adjustments	6	6	4	1		Ç	

### Service life

As it is not possible to establish a maximum number of uses (that may be determined by many parameters such as duration of use, hardness of tissue, the force applied, wear), we recommend that medical devices being routinely used are replaced at least once a year. Replace the medical device if the tip does not vibrate at the expected frequency, the treatment is not progressing as normal and is taking longer or is at a standstill.

### **Associated documentation**

Document title	References
Consulting electronic user instructions	J00007
Cleaning, disinfection and sterilisation instructions for tips	J02001
Endosuccess Apical Surgery Kit clinical tips	J08161
Ultrasonic generator power settings table	J58000
General instructions relating to the complete range of standard ultrasonic dental tips	J02101







### **Sterilisation**



Sterilise prior to each use



The tips must be cleaned, disinfected and sterilised prior to each use. Prior to each use, please refer to the cleaning, disinfection and sterilisation instructions for tips J02001.




The practitioner has to continually monitor the clinical site to immediately identify any heating risk.


#### Tip | AS9D | J00461 | (09) | V3 | 05/2021 | NB15EN040C

SATELEC|A Company of ACTEON Group 17 av. Gustave Eiffel| ZI du Phare 33700 MERIGNAC|FRANCE Tel. +33 (0) 556 34 06 07|Fax. +33 (0) 556 34 92 92 satelec@acteongroup.com|www.acteongroup.com

## **Installation**



## **Disassembly**



## Manufacturer identification



SATELEC

A Company of ACTEON Group 17, avenue Gustave Eiffel

ZI du Phare 33700 MERIGNAC

France

Tel. +33 (0) 556.34.06.07

Fax. +33 (0) 556.34.92.92

E.mail: satelec@acteongroup.com

www.acteongroup.com

# **Date of first CE marking**

2009





CE Warking